www.tradeshowdisplayoutlet.com

TSDO | Trade Show Display Outlet Curved Tension Fabric Display Assembly Instruction's


Note: Assembly is the same for all sizes of curved Companion LT displays







2. Assemble bungied poles.



3. Connect large bungled poles to corners, matching up shapes.




4. Insert center support pole.



5. Pull pillowcased graphic over the frame.



6. Zip up the bottom of graphic.



7. Clamp optional lights on top bar. Tip: Put lights on before standing the display up.



Troubleshooting: How to Straighten your Frame







Have two people hold the sides of the frame, then gently twist until the frame is straight.